

澄清问题

序号 No.	参考文件 References	页码 Page number	编号/内容 No./Content	澄清问题: Clarification:
	VOLUME-II: EMPLOYER'S REQUIREMENTS Part-II: Technical Provisions	Page No 2-9	2.2.4.4.6 Drums “ Double layer of rope winding shall not be allowed when the hook is at highest position.”	It is suggested to amend to:“No more than 3 layers of rope winding shall be allowed when the hook is at highest position.” Please confirm whether this proposal is acceptable.
				Provide a location relationship diagram in CAD format of the Power Plant building and the 132KV open-air step-up substation with detailed distance scales, so as to measure the length of the phase-separated busbar from the generator outlet to the low-voltage side of the main transformer.